TEST REPORT

No. : GZIN2510001940CM02-1_EN

Date : 2025-11-25

Scan to see the report

GZIN2510001940CM02-1

Verification:
check.sgsonline.com.cn

CUSTOMER NAME: GUANGDONG FORTUNE STONE NEW MATERIAL CO.,LTD

ADDRESS: LUO YANG JIE DAO LI CUN XIAO DENG LONG DA XIANG XIN WU YANG GOU GROUP, BOLUO COUNTY, HUIZHOU CITY,GUANGDONG PROVINCE, CHINA

Sample Name : Flexible Stone

Buyer : micro sine electric sl

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

****

SGS Ref. No. : GZIN2509003897PL07

Date of Receipt : 2025-10-23

Testing Period : 2025-10-23 ~ 2025-11-25

Test result(s) : For further details, please refer to the following page(s)
(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch.

Tobby Yang
Authorized signatory

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Commercial Inspection & Testing Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

No. : GZIN2510001940CM02-1_EN

Date : 2025-11-25

Summary of Results:

No.	Test Item	Test Method	Result
1	Dirt Pickup Resistance and Stain Removal	GB/T 9780-2013 Section 5.4	$X_{Exterior}$ =12%

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国・广东・广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

TEST REPORT

1. Test Item: Dirt Pickup Resistance and Stain Removal

Sample Description: A-Sheet

Test Method: GB/T 9780-2013 Section 5.4

Test Condition:

Test Method: Section 5.4 Painting - Method A (Standard Condition)

Method A:

Step 1: Brush method, the pollution source suspension is composed of standard test ash and water with weight ratio of 1:1, the brushing amount is (0.7 ± 0.1) g for each piece of specimen.

Step 2: Place the specimens under the standard test condition for 2h and then open the valve of the flushing device filled with 15L of water to the maximum, rinse the specimen for 1minute and close the valve. Then place the specimens under the standard test condition for about 22h.

Step 1 to step 2 as 1 cycle, total 5 cycles.

Lab Environmental Condition: (23 ± 2) °C, (50 ± 5) %RH

Test Result:

Sample	Decrease Rate of Reflection Coefficient of Coatings on Exterior Wall
A	12%

Note:

1. $X_{Exterior} = |A-B|/A \times 100\%$

$X_{Exterior}$—Decrease rate of reflection coefficient of coatings on exterior wall;

A—Initial average reflection coefficient of coatings;

B—Average reflection coefficient of coatings after contamination test.

2. Reflection coefficient was measured by sphere spectrophotometer d/8° under D65 standard light source and with 10° observer. SCI: include specular component reflection condition, 25mm aperture.

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Commercial Inspection Testing Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com




Member of the SGS Group (SGS SA)

TEST REPORT

No. : GZIN2510001940CM02-1_EN

Date : 2025-11-25

Test Photo:

<table>
<tr><td>
</td><td>
</td></tr>
<tr><td>Original Sample-Sample A</td><td>Before Test-Sample A</td></tr>
<tr><td colspan="2">
</td></tr>
<tr><td colspan="2">After Test-Sample A</td></tr>
</table>

Appendix information:

1. This test report deletes Manufacturer, supersedes the test report No. GZIN2510001940CM02_EN dated Nov 25th, 2025, original report will be invalid from today.
2. The test report shall only be used for client scientific research, teaching, internal quality control, product research and development, etc. and just for client internal reference.

******** End of report********

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Commercial Vehicle Testing Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com
Member of the SGS Group (SGS SA)