# TEST REPORT

**No. : GZIN2509001820CM05-1_EN**
**Date : 2025-11-25**
**Page: 1 of 3**

Scan to see the report
GZIN2509001820CM05-1
Verification:
check.sgsonline.com.cn

CUSTOMER NAME: GUANGDONG FORTUNE STONE NEW MATERIAL CO.,LTD

ADDRESS: LUO YANG JIE DAO LI CUN XIAO DENG LONG DA XIANG XIN WU YANG GOU GROUP, BOLUO COUNTY, HUIZHOU CITY,GUANGDONG PROVINCE, CHINA

| | | |
|---|---|---|
| Sample Name | : | Flexible Stone |
| Buyer | : | micro sine electric sl |

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

**********

| | | |
|---|---|---|
| SGS Ref. No. | : | GZIN2509003897PL09 |
| Date of Receipt | : | 2025-09-30 |
| Testing Period | : | 2025-09-30~2025-10-13 |
| Test result(s) | : | For further details, please refer to the following page(s)<br>(Unless otherwise stated the results shown in this test report refer only to the sample(s) tested) |

Signed for
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch.

Tobby Yang
Authorized signatory

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国・广东・广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

# TEST REPORT

**No. : GZIN2509001820CM05-1_EN**


**Date : 2025-11-25**



Summary of Results:

| No. | Test Item | Test Method | Result |
|---|---|---|---|
| 1 | Radioactivity | GB 6566-2010 | See results |

Original Sample Photo:



Sample

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国・广东・广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

# TEST REPORT

**No. : GZIN2509001820CM05-1_EN**

**Date : 2025-11-25**



Test Item: Radioactivity

Sample Description: See photo

Test Method: GB 6566-2010

Test Condition:

Specimen: Powder, made from original sample

Test Result:

| Test item | | Test Result |
|---|---|---|
| Specific activity | Ra-226 | 2.73 Bq/kg |
| | Th-232 | 6.17 Bq/kg |
| | K-40 | 12.87 Bq/kg |
| Internal exposure index $I_{Ra}$ | | <0.1 |
| External exposure index $I_r$ | | <0.1 |

Classification according to GB 6566-2010: Class A decorative materials

Note: Class A decorative materials: The samples meeting both $I_{Ra}$≤1.0 and $I_r$≤1.3 are identified as Class A decoration materials.

Appendix information:

1. This test report deletes Manufacturer, supersedes the test report No. GZIN2509001820CM05_EN dated Nov 25th, 2025, original report will be invalid from today.
2. The test report shall only be used for clients' scientific research, teaching, internal quality control, product research and development, etc., and just for internal reference.
3. Unless otherwise stated, this report provides a declaration of conformity according to whether the test results are within the specified limits or specifications without considering the measurement uncertainty.

********End of report********

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Comprehensive Technical Services Laboratory

检验检测专用章 Inspection & Testing Services

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

Member of the SGS Group (SGS SA)