TEST REPORT

No. : GZIN2510001940CM01-1_EN

Date : 2025-11-25

Scan to see the report

GZIN2510001940CM01-1

Verification: check.sgsonline.com.cn

CUSTOMER NAME:		GUANGDONG FORTUNE STONE NEW MATERIAL CO.,LTD
ADDRESS:		LUO YANG JIE DAO LI CUN XIAO DENG LONG DA XIANG XIN WU YANG GOU GROUP, BOLUO COUNTY, HUIZHOU CITY,GUANGDONG PROVINCE, CHINA
Sample Name	:	Flexible Stone
Buyer	:	micro sine electric sl

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

****

SGS Ref. No.	:	GZIN2509003897PL03
Date of Receipt	:	2025-10-23
Testing Period	:	2025-10-23 ~ 2025-11-25
Test result(s)	:	For further details, please refer to the following page(s) (Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch.

Tobby Yang
Authorized signatory

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国・广东・广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT


No. : GZIN2510001940CM01-1_EN

Date : 2025-11-25

Summary of Results:

No.	Test Item	Test Method	Result
1	Temperature change resistance of architectural coatings	JG/T 25-2017 and client's requirement	See results

Original Sample Photo:



Sample

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

TEST REPORT

No. : GZIN2510001940CM01-1_EN

Date : 2025-11-25

Test Item: Temperature change resistance of architectural coatings

Sample Description: See photo

Test Method: JG/T 25-2017 and client's requirement

Test Condition:

Specimens: 150 mm×70 mm×7 mm, 3 pcs

Condition: ①Immerse in 23℃ water for 18h→②Freeze at -18℃ for 3h→③Dry at 50℃ for 3h→②→③as a cycle, 3 cycles in total

Test Result:

Test Item	Test Result
Temperature change resistance of architectural coatings	No powdering, crack, peeling or blistering. No obvious change in color.

Appendix information:

1. This test report deletes Manufacturer, supersedes the test report No. GZIN2510001940CM01_EN dated Nov 25th, 2025, original report will be invalid from today.
2. The test report shall only be used for clients' scientific research, teaching, internal quality control, product research and development, etc., and just for internal reference.

********End of report********

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Commercial Inspection Testing Laboratory

检验检测专用章 Inspection & Testing Services

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

Member of the SGS Group (SGS SA)